

# 312 BG Universal Synthetic ATF APPLICATION CHART

BG Universal Synthetic ATF, PN 312, meets or exceeds the performance requirements of the following automatic transmission fluids.

31 luglio 2017

| MAKE                   | ATF PN   |
|------------------------|--|
| <b>Acura</b>           | ATF-Z1, DW-1, TYPE 3.0 PN 08200-9016A, TYPE 2.0 PN 082009015A, TYPE 3.1 PN 08200-9017A   |
| <b>Aisin Warner</b>    | AW-1, AS69RC, 05189966AB, 05189977AA   |
| <b>Alfa Romeo</b>      | ALL  |
| <b>Allison</b>         | C-3, C-4, John Deere HD SynTran, <sup>TM</sup> Mobil Delvac Synthetic ATF <sup>TM</sup>  |
| <b>American Motors</b> | ALL  |
| <b>Aston Martin</b>    | ALL  |
| <b>Audi</b>            | G052025A2, G052162A1, G052162A2, LT71141, G055025A2, G055005A2, G055162A2, G060162A2, G055005A6, G052990A2, G055540A2  |
| <b>Bentley</b>         | ALL INCLUDING PY112995PA   |
| <b>BMW</b>             | LA2634, LT71141, 81229400275, 83220142156, 83220403248, 83220403249, 83229407765, 83229407807, 83220024359, 83220026922, BMW807, TEXACO ETL-7045E, TEXACO ELT-8072B, 83220142516, 705/ATFD-3, 83220402413, 83220397114, 83222152426, 83227542290, 83222163514, 83222220445 (1375.4), 83222289720 |
| <b>Caterpillar</b>     | TO-2   |
| <b>Chrysler/Mopar</b>  | ATF 7176, +2, +3 (MS-7176E), +4 (MS-9602), AS68RC, AS69RC, 05127382AB, 05189966AB, 05189966AA, 05189977AA, 05127382AA, 68157995AA, 68157995AB, 68218925AA, 68171866, 68171869AB  |
| <b>Citroen</b>         | 973622, Z000169756   |
| <b>Daewoo</b>          | ALL INCLUDING LT71141  |
| <b>Diwa</b>            | ALL  |
| <b>Esso</b>            | ATF LT 71141   |
| <b>Fiat-Lancia</b>     | ALL  |
| <b>Ford</b>            | MERCON <sup>®</sup> (XT-2-QDR OR XT-2-QSM), MERCON <sup>®</sup> SP (XT-6-QSP), MERCON <sup>®</sup> V (XT-5-QM), MERCON <sup>®</sup> LV(XT-10-QLV), PREMIUM AUTOMATIC TRANSMISSION FLUID (XT-8-QAW), FNR5 AUTOMATIC TRANSMISSION FLUID (XT-9-QMM5), X-2-QDX                                       |
| <b>Fuchs</b>           | Titan ATF 3292, Titan ATF 3353   |
| <b>General Motors</b>  | DEXRON <sup>®</sup> , DEXRON <sup>®</sup> -II, -IID, -IIE, -III, -IIIG/H, DEXRON <sup>®</sup> -VI, GM T-IV (PN 88900925), 9986195  |
| <b>Honda</b>           | ATF-Z1, DW-1, TYPE 3.1 08200-9017, 08200-9015  |
| <b>Hyundai</b>         | SP-II, SP-III, SPH-IV (00232-19045), 040000C90SG, NWS-9638, SPH-IV-RR, 00232-19012, 00232-19015, 00232-19016, 00232-19023, 00232-19024, SP4-M, JWS-3309 T-4, 00232-19057, 00232-19059, NWS-9638 T5   |
| <b>Idemitsu</b>        | K17, JATCO 3100 PL085, W0133-19031-54  |
| <b>Infiniti</b>        | ALL INCLUDING MATIC D, J, K, S   |
| <b>Isuzu</b>           | ALL  |
| <b>Jaguar</b>          | ATF 3403 M115, C2C8432, 1X43 2C9010AA, JLM 20237, JLM 20238, LT71141, JATCO 3100 PL085, JDE 26444  |
| <b>JASO</b>            | 1A   |
| <b>Jeep</b>            | SEE CHRYSLER/MOPAR   |
| <b>JWS</b>             | 3309, 3314, 3317, 3324   |

| MAKE                         | ATF PN   |
|------------------------------|--|
| <b>Kia</b>                   | SP-II, SP-III, RED 1, SP IV, UM090-CH042 (TYPE 4 SP-IV), ATF TYPE 4(M)   |
| <b>Land Rover</b>            | ESSO LT71141, TEXACO N402, TYK500050, LRN 13754, TEXACO ETL-7045E, STC 4863, STC 505.31, LR 002748, LR 023288, LR 023289   |
| <b>Lexus</b>                 | ALL  |
| <b>Man</b>                   | 339F, 339V1, 339V2, 339Z1, 339Z2, 339Z3  |
| <b>Maserati</b>              | 231603   |
| <b>Matra</b>                 | ALL  |
| <b>Mazda</b>                 | ATF-M III, ATF-MV, ATF-FZ, 0000-77-112E-01, 0000-77-120E-05, 0000-77-114E-01, 0000-FZ-113E-01  |
| <b>Mercedes Benz</b>         | 236.1, 236.2, 236.3, 236.5, 236.6, 236.7, 236.8, 236.9, 236.10, 236.11, 236.12, 236.14, 236.41, 236.81, 0019892103, SHELL 3403-4 115, A0019892203, 0019894503, ATF 4134, 0019896803                        |
| <b>Mitsubishi</b>            | DIAMOND SP, SP-II, SP-III, SP-IV, J2, J3   |
| <b>Nissan</b>                | MATIC D, J, K, S, 402  |
| <b>Opel</b>                  | ALL  |
| <b>Peugeot</b>               | 973622, Z000169756   |
| <b>Porsche</b>               | 99991754700A2, 00004320509, 00004320441, SHELL 3403 M115, 99991754700, 000 043 205 28  |
| <b>Renault</b>               | 7711218368   |
| <b>Rolls Royce</b>           | PL31493 PA   |
| <b>Saab</b>                  | 93160372, 93160393, 93165147   |
| <b>Saturn</b>                | 22689186, ALL  |
| <b>Shell</b>                 | LA2634, ATF 3353, ATF 3403, M115, M-1375.4, M-1375.5, M-1375.6, M-L12108   |
| <b>Subaru</b>                | SOA868V9241, K0140Y0700, ATF-HP, HP/PS (SOA427V1500 HP), ALL   |
| <b>Suzuki</b>                | 99980-06000, ATF 3317 SP-4B, 990B0B-01001, 3314, ALL   |
| <b>Texaco</b>                | ETL-7045E, ETL-8072B, N402   |
| <b>Toyota</b>                | TYPE T, T-II, T-III, TYPE T-IV, TOYOTA WS  |
| <b>Voith</b>                 | 55.6335.XX (G607), 55.6336.XX (G1363)  |
| <b>Volvo</b>                 | 97340, 97341, 97342, 3344208, 31256774, 31256775, 31256776, 1161521, 1161540, 1161640, 1161621,  |
| <b>Volkswagen</b>            | G055025A2, G055162A2, G052162A2, G052990A2, G052025A2, G052162A1, G055005A6, LT71141, G055005A2, G060162A2, G055540A2  |
| <b>ZF Friedrichshafen AG</b> | TE-ML: 02F, 03D, 04D, 05L, 09, 11A, 11B, 14A, 14B, 14C, 16L, 17C, SHELL LA 2634, LT 71141, LifeGuard Fluid 6 (S671090255), LifeGuard Fluid 6 Plus (S671090281), LifeGuard Fluid 8 (AA00601304, S671090312) |

**BG Universal Synthetic ATF is not recommended for use in the following applications:**

Continuously Variable Transmissions (CVTs)

Dual Clutch Transmissions (DCT)

Direct-Shift Gearbox (DSG)

Ford Type F

GM DEXRON®-HP

All Mercedes Benz 722.9 transmissions built after June 21, 2010 requiring ATF A0019897803 (236.15)

**BG Products, Inc., accepts no liability for excessive use or misuse of this product.**

**Revision date** 7-27-17

**Revisions** Added to Honda section  
- 08200-9015

**4-4-17** Added to BMW section  
- 83222289720

**1-19-17** Added to Land Rover section  
- LR 023289

**12-9-16** Revised Ford and GM sections  
- Removed spaces after MERCON®  
- Added hyphens after DEXRON®

**10-20-16** Added to Acura  
- TYPE 3.1 PN 08200-9017A

**8-23-16** Added to Acura  
- TYPE 2.0 PN 082009015A

**5-5-16** Added to Not Recommended section  
- GM Dexron HP

**4-28-16** Added to Land Rover:  
- LR 023288

**3-17-16** Added to Chrysler/Mopar:  
- 68171869AB

**Added to Honda:**  
- TYPE 3.1 08200-9017

**1-25-16** Added to Aisin Warner  
- AS69RC, 05189966AB, 05189977AA

**Added to Chrysler/Mopar**  
- AS69RC, 05189966AB

**1-5-16** Added to Acura  
- TYPE 3.0 PN 08200-9016A

**Added to BMW**  
- 83222220445 (1375.4)

- 7-20-15 Added to Land Rover:**  
- LR 023288
- 7-13-15 Changed Acura:**  
- REMOVED "ALL" ADDED "ATF-Z1, DW-1"
- Added to Fuchs:**  
- Titan ATF 3353
- Added to Hyundai:**  
- 00232-19057, 00232-19059
- Removed from Hyundai:**  
- T-5
- Added to Mercedes Benz:**  
- 236.41, 236.81
- 6-25-15 Added to Allison:**  
- John Deere HD SynTran™  
- Mobil Delvac Synthetic ATF™
- 5-18-15 Added this PN to Chrysler/Mopar:**  
- 68171866
- 3-27-15 Added this PN to Kia:**  
- ATF TYPE 4(M)
- 3-9-15 Added "(S671090312)" to LifeGuard Fluid 8**  
under ZF Friedrichshafen AG
- 10-28-14 Removed "ALL" from Jeep. Replaced with:**  
- See Chrysler/Mopar
- 10-1-14 Added this ATF PN from Chrysler/Mopar:**  
- 68218925AA
- Added this ATF PN from Fuchs:**  
- Titan ATF 3292
- 9-3-14 Removed these ATF PN's from Allison:**  
- TES-295  
- TES-389

**8-28-14 Added these ATF PN's to Volvo:**

- 31256775
- 31256776

**8-13-14 Added these ATF PN's to Mazda:**

- ATF-FZ
- 0000-FZ-113E-01

**6-12-14 Added this ATF PN to Subaru:**

- HP/PS (SOA427V1500 HP)